



This initial notification information is required by Section 103(c) of the Comprehensive Environmental Response, Compensation, and Liability Act of 1980 and must be mailed by June 9, 1981.

Please type or print in ink. If you need additional space, use separate sheets of paper. Indicate the letter of the item which applies.

plies. 81 06 05
MN#50 MNS-000-001-100

Enter the name and address of the person or organization required to notify.

Name	Inland Steel Mining Company			
Street	1701 North 9th Avenue, P.O. Box 1001			
City	Virginia	State	MN	Zip Code 55792

Enter the common name (if known) and actual location of the site.

Name of Site St. Paul Mine

City KEEWATIN County ST. LOUIS State IA Zip Code 55009

Enter the name, title (if applicable), and business telephone number of the person to contact regarding information submitted on this form.

Name (Last, First and Title) Ricciardi, Michael - Sr. Environmental Engineer

Phone (218) 749-8210

Enter the years that you estimate waste treatment, storage, or disposal began and ended at the site.

From (Year) 1956 To (Year) 1964

EPA Region 5 Records Ctr.



315326

Option I: Select general waste types and source categories. If you do not know the general waste types or sources, you are encouraged to describe the site in Item I—Description of Site.

Place an X in the appropriate boxes. The categories listed overlap. Check each applicable category.

Place an X in the appropriate boxes.

1. ☐ Organics
2. ☐ Inorganics
3. ☐ Solvents
4. ☐ Pesticides
5. ☐ Heavy metals
6. ☐ Acids
7. ☐ Bases
8. ☐ PCBs
9. ☐ Mixed Municipal Waste
10. ☒ Unknown
11. ☐ Other (Specify)

1. ☐ Mining
2. ☐ Construction
3. ☐ Textiles
4. ☐ Fertilizer
5. ☐ Paper/Printing
6. ☐ Leather Tanning
7. ☐ Iron/Steel Foundry
8. ☐ Chemical, General
9. ☐ Plating/Polishing
10. ☐ Military/Ammunition
11. ☐ Electrical Conductors
12. ☐ Transformers
13. ☐ Utility Companies
14. ☐ Sanitary/Refuse
15. ☐ Photofinish
16. ☐ Lab/Hospital
17. ☒ Unknown
18. ☐ Other (Specify)

Option 2: This option is available to persons familiar with the Resource Conservation and Recovery Act (RCRA) Section 3001 regulations (40 CFR Part 261).

EPA has assigned a four-digit number to each hazardous waste listed in the regulations under Section 3001 of RCRA. Enter the appropriate four-digit number in the boxes provided. A copy of the list of hazardous wastes and codes can be obtained by contacting the EPA Region serving the State in which the site is located.

[illegible]

Form Approved
OMB No. 2000-0138
EPA Form 8900-1

000033 JUN-581

JUN 10 1981

Notification of Hazardous Waste Site

Side Two

F Waste Quantity:

Place an X in the appropriate boxes to indicate the facility types found at the site.

In the "total facility waste amount" space give the estimated combined quantity (volume) of hazardous wastes at the site using cubic feet or gallons.

In the "total facility area" space, give the estimated area size which the facilities occupy using square feet or acres.

Facility Type UNKNOWN

1. ☐ Piles
2. ☐ Land Treatment
3. ☐ Landfill
4. ☐ Tanks
5. ☐ Impoundment
6. ☐ Underground Injection
7. ☐ Drums, Above Ground
8. ☐ Drums, Below Ground
9. ☐ Other (Specify) _____

Total Facility Waste Amount

cubic feet _____

gallons _____

Total Facility Area

square feet _____

acres _____

G Known, Suspected or Likely Releases to the Environment: UNKNOWN

Place an X in the appropriate boxes to indicate any known, suspected, or likely releases of wastes to the environment.

☐ Known ☐ Suspected ☐ Likely ☐ None

Note: Items H and I are optional. Completing these items will assist EPA and State and local governments in locating and assessing hazardous waste sites. Although completing the items is not required, you are encouraged to do so.

H Sketch Map of Site Location: (Optional)

Sketch a map showing streets, highways, routes or other prominent landmarks near the site. Place an X on the map to indicate the site location. Draw an arrow showing the direction north. You may substitute a publishing map showing the site location.

I Description of Site: (Optional)

Describe the history and present conditions of the site. Give directions to the site and describe any nearby wells, springs, lakes, or housing. Include such information as how waste was disposed and where the waste came from. Provide any other information or comments which may help describe the site conditions.

J Signature and Title:

The person or authorized representative (such as plant managers, superintendents, trustees or attorneys) of persons required to notify must sign the form and provide a mailing address (if different than address in item A). For other persons providing notification, the signature is optional. Check the boxes which best describe the relationship to the site of the person required to notify. If you are not required to notify check "Other".

Name Samuel A. Reipas, Vice President, OperationsStreet 1701 North 9th AvenueCity Virginia State MN Zip Code 55792Signature Date 5-27-81

- ☒ Owner, Present
☐ Owner, Past
☐ Transporter
☐ Operator, Present
☐ Operator, Past
☐ Other

Copy 15



Inland Steel Mining

June 5, 1981

United States Environmental Protection Agency
Region V
Sites Notification
Chicago, IL 60604

Gentlemen:

Enclosed are fifteen (15) completed Notification of Hazardous Waste Site forms. The notification forms for Inland Steel Mining Company - Minorca Mine, Jackson County Iron Company and Inland Lime and Stone Company have been completed based on actual knowledge of deposition of waste at the respective sites. The remaining twelve (12) notification forms have been completed with no conclusive past or present knowledge of any hazardous waste deposited at these sites. Rather the following assumptions have been developed in order to complete the forms:

Assumption #1: Certain present day mining operations use solvents and leaded greases during routine maintenance of mining equipment.

Assumption #2: Similar products were probably used during early mining operations.

Assumption #3: If spent residues from these products were generated, it is possible that they may have been deposited at the site rather than hauled away.

Therefore, the remaining twelve (12) notifications are submitted in accordance with the Superfund regulations since it is possible that hazardous wastes may have been deposited at these sites.


JUN 10 1981

US EPA

Page 2

In all probability it is highly unlikely that large amounts of hazardous waste were generated at these sites since these operations were very small with limited mining equipment compared to today's mining operations and equipment. However, if you have any questions on the notification forms, please do not hesitate to call Michael Ricciardi at (218) 749-8210.

Sincerely,



Samuel A. Reipas
Vice President - Operations

SAR:mlr

Enclosure

JUN 10 1981

6/5



121 116-424 #116-424
SEE ME JES

FIRST CLASS



FACILITY ID NUMBER MNS000001100		COMPANY NAME	
COMPANY ADDRESS		CITY	STATE ABBREV:
			ZIP CODE
CONTACT PERSON'S NAME/TITLE		TELEPHONE NUMBER (INCLUDE AREA CODE) 	

[illegible]